





























PROJETO MONITORAMENTO IPIRANGA

MONITORAMENTO DAS DIVISAS - ENTRADA E SAÍDA

-  CAM1
-  CAM 2 E 3
-  CAM 4 5 6
-  CAM 7
-  CAM 8 e 9
-  CAM 10 e 11
-  CAM12 E 13
-  CAM 13 e 14
-  CAM 15, 16 e 17
-  CAM 18, 19 e 20
-  CAM 21, 22 e 23
-  CAM 24 e 25
-  CAM 26 e 27
-  CAM 28 e 29
-  CAM 30, 31 e 32
-  CAM 33
-  CAM 34 e 35
-  CAM 36 e 37
-  CAM 38 e 39
-  CAM 40 e 41
-  CAM 42
-  CAM 43 e 44
-  CAM 45
-  CAM46
-  CAM 47, 48 49 e 50
-  CAM 51 e 52

BAIRRO IPIRANGA

-  Linha 1
-  Linha 2

Projeto de Câmeras de Monitoramento do Bairro Ipiranga

